





CMR Electrical Ltd
Bolton House
Five Chimneys Lane
Hadlow Down
East Sussex
TN22 4DX
Tel: 01825 733600

PPS

Pipe in Pipe Leak Detection Sensor Installation and Operation Manual



Sensor wiring



Connections

Red Wire = 12-24VAC live or 13-24VDC +
Black Wire = Volt free Contact common
Yellow Wire = Volt Free Contact Normally Open, Close in alarm
Blue Wire = 12 - 24VAC Neutral or 13 - 24VDC negative

The signal cable should be terminated between the sensor and the main Alarm/BMS in the following manner.

Connection to Signal Cable	Signal cable wire colour
+VDC/AC	Red
0VDC/AC	Blue
Contact N/O	Yellow
Contact N/O	Black